



2016 Bridge Inspections

Town of Gananoque

- June 2016 -



Keystone Bridge Management Corp.

Contents

Introduction	1
Capital Needs.....	1
Rail to Trail Bridge	2
Hudson Bridge	2
King Street Pedestrian Bridge.....	3
Bridge Maintenance	3
Performance Deficiencies.....	4
Triple-D Inspections	4
Understanding the Inspection Forms.....	5
Defects	6
Damage.....	7
Maintenance	7
Capital Recommendation.....	7
Performance	7
Note.....	7
Capital Needs Cost Estimate Breakdown	8
Inspection Images	8
Digital Copy.....	8
Limitations	9
Closing	10

Introduction

Keystone Bridge Management Corp. was retained by the Town of Gananoque to provide assessments for all of its bridges. The field work was completed on May 5, 2016 by Messrs. John Landry, and Steve Reid, C.E.T. Also assisting was Cole Zanchetta, a third year civil engineering student. A total of nine bridges were inspected of which three were road bridges and the remainder pedestrian bridges.

Biennial inspection of bridges and culverts with a span equal to or exceeding 3.0 metres is mandated by provincial statute in Ontario. The legislation is found in the Public Transportation and Highway Improvement Act. Most municipalities in Ontario comply with this legal requirement. Municipalities seeking provincial funding for structure capital improvements are required to demonstrate their bridges receive a biennial inspection. Increasingly, the government is expecting municipalities to have an asset management plan as well.

A biennial bridge inspection is prescribed to follow the Ontario Structure Inspection Manual, OSIM. However the regulations (O.Reg.104/97) allow variations from OSIM where:

- (a) the variation is not a marked departure from the Ontario Structure Inspection Manual; and**
- (b) the variation does not adversely affect the safety and mobility of people and goods. O. Reg. 472/10, s. 2.**

Keystone Bridge Management Corp. has created a significant improvement to conventional OSIM reporting. Keystone's proprietary approach complies with the spirit and intent of the Regulation, but takes bridge inspection and management an order of magnitude beyond that contemplated in OSIM. Keystone has eliminated most of the subjectivity associated with the Excellent, Good, Fair, Poor rating system of OSIM. Keystone utilizes a deterministic depreciation model to describe the transition of a bridge from excellent to fair, and supplements this by noting damage and defects in components at the time of inspection. This approach complements modern asset management practises. It is something that OSIM on its own cannot do.

Capital Needs

The capital needs were estimated with an estimating tool contained in the Keystone Bridge Management System. This utility covers common items that include deck replacement, expansion joint replacement, barrier wall replacement, waterproofing and paving. The utility provides guidance for traffic management costs. All costs are marked up 20% to account for contingencies and engineering. Contract administration costs are not included.



The Capital Needs for the Town of Gananoque are summarized in a separate included report appended at the end of this Report.

The **Capital Needs Report** is organized from the most immediate needs to the less immediate needs by the Recommended Year sub-headings. Two capital needs pictures are graphically presented at the end of the Report. A Grand Total of **\$4,916,000** is the projected capital need from the present to 2020.

The capital needs identify two structures that ideally should be replaced in the next five years or so. This is described further in the following sub-headings.

The King Street Pedestrian Bridge is also discussed further.

Rail to Trail Bridge

This bridge is located immediately upstream of the dam. It consists of three spans of a railway bridge that was converted to pedestrian use. The girder ends at the piers and abutments are exhibiting severe corrosion with perforation. The west end of this bridge is experiencing web crippling of the girders and is slowly failing.

The bridge is still safe for pedestrian use but could “settle” due to girder web failure, and result in alarm to the public. It would be prudent for the Town to not risk losing the public’s confidence in this trail bridge by replacing it before the girder webs fail much further.

Hudson Bridge

The Hudson Bridge was load tested in 2014. Further information regarding this bridge is provided in the load testing report.

The Hudson Bridge is exhibiting severe corrosion and rust perforation of its primary structural components such as the floor beams and truss compression members. As it continues to corrode it is becoming increasingly structurally unreliable. It should not be relied on to carry traffic of any description after 2030. Until then it can be managed by load posting. However, the Town is assuming some risk by continuing to maintain the bridge open to traffic. Ideally the bridge should be taken out of service and replaced with a modern bridge. The recommended year of 2020 is flexible and represents a reasonable time for the Town to respond and obtain funding for a replacement bridge.

The historical attributes of this bridge could be retained by repurposing the bridge as a pedestrian bridge. However the bridge would require significant reworking and restoration before it is repurposed as anything other than a museum artifact.

King Street Pedestrian Bridge

This bridge is located immediately downstream of the King Street Bridge. It is a two span railway through-plate girder bridge repurposed as an exceptionally wide pedestrian bridge.

The wood deck of this bridge experienced a punching type failure from a maintenance vehicle the past winter. Further investigation of the failure revealed decay of the deck planking and it is suspected that the supporting wood stringers are also experiencing scattered decay.

It is recommended to plan on replacing the timber deck by 2018.

The remainder of the bridge has been largely neglected and is in a state of very poor repair. There are gaping holes from corrosion in parts of the bridge's floor system. When this level of severe corrosion is visible from standing beneath the bridge, one has to wonder how severe the corrosion is in other less visible areas of the bridge.

The Town should close this bridge in the winter so that further salt exposure can be reduced.

This bridge deserves a very comprehensive detailed inspection to more fully assess the condition of inaccessible areas of the bridge. Only a detailed assessment such as this can be relied on to better determine the fate of the bridge.

In the absence of better information, it is recommended that the Town plan on closing the King Street Pedestrian Bridge by not later than 2025.

The capital needs groupings in the Capital Needs Report suggests relative priority, but other considerations such as traffic demand, risk of failure, and combining projects should also be considered to establish actual priorities.

The capital estimates provided are very approximate. Environmental considerations, difficult foundations, dewatering requirements, and traffic management costs can be very significant variables that can only be estimated accurately at the preliminary design stage.

Bridge Maintenance

Detailed maintenance needs are captured in the **Bridge Maintenance Report** appended at the end of this Report.

Bridge cleaning is widely recognized as an important maintenance activity. Ideally spring maintenance should include a thorough sweeping of the bridges' horizontal



surfaces, and power washing of the bridge seats especially where expansion joints are open or the seal is compromised. Early sweeping removes brine laden winter sand from the bridge decks. This greatly helps forestall the onset of corrosion of the reinforcing steel. Expansion joints should be cleaned of debris caught inside the gaps in the spring and fall of each year.

The Hudson Bridge is in urgent need of a very thorough cleaning in order to reduce the present rate of corrosion.

Performance Deficiencies

The various components in and around a structure all have a purpose or functionality. Where the purpose or functionality is compromised, it is recorded as a performance deficiency. Appended at the end of this report is a Performance Deficiencies Report.

These deficiencies are often difficult or expensive to remedy. Ideally, a replacement structure should address the present performance deficiencies. These deficiencies should be reviewed when prioritizing the capital program.

Performance Deficiencies require risk management strategizing by the owner.

Triple-D Inspections

The individual bridge inspection reports are provided separately from this Summary Report. The reports are a slight departure from OSIM Reports in that the field inspection effort is directed at identifying deterioration and performance issues as explained below.

Keystone's approach to Bridge Management is fundamentally different from all others anywhere in the world. Keystone models bridge assets in terms of their **D**epreciation, **D**efects, and **D**amage. This "**Triple-D**" approach is unique to Keystone, and is the soundest and most reliable method ever conceived to accurately ascertain or predict the condition of a bridge.

The "**Triple-D**" approach is imbedded in a highly sophisticated MS Access database application developed by Keystone. The design of the database easily facilitates porting the data to any other application, and is highly customizable to any client.

Every bridge is modeled in terms of its components. Each component has a life expectancy and value based on its material and geometric properties. As a bridge ages, the components depreciate in accordance with a simple depreciation function that is client specified. Either a straight-line or parabolic depreciation function is recommended. The overall depreciation of a structure is expressed in terms of the sum of the depreciation of all the components.



This deterministic approach to assessing the condition of a bridge provides an extremely reliable, reproducible and predictable approach to stating the condition of not only a bridge, but an entire bridge inventory.

Imagine a municipality that was incorporated in 1900. Every year on its anniversary it builds an identical bridge, for 100 years running until 2000. For simplicity, presume each bridge is constructed of only one component, and the deemed life of that component is exactly 100 years. From this example, it is easy to see that the oldest bridge constructed in 1901 has completely depreciated and now has zero value. Whereas, the centennial bridge constructed in 2000 would on its completion retain its full value. If straight line depreciation is assumed, the centennial bridge would be depreciated to 91% of its original value in 2009. In 2001, the depreciation of the entire bridge inventory of 100 bridges would be 50% assuming straight-line depreciation. It is this simple straight-forward approach that Keystone has adopted.

Defects are any relatively benign but unintended changes to a bridge that cannot be attributed to normal wear and tear, or aging. Mild to moderate scaling of a concrete surface is an example of a **Defect**. Early alkali-aggregate reactivity in concrete is another example of a **Defect**. **Damage** is any change to a structure that reduces the section properties or intended performance of a structural component. **Damage** includes spalling, delamination, disintegration or severe cracking of concrete; plastic deformation or gouging of steel, or decay of timber.

Defects and **Damage** are detected, quantified, qualified and recorded when the bridge is inspected. The **Depreciated** value of a component is adjusted to account for **Defects** or **Damage**. Keystone recommends that any component that is more than 20% **Damaged** is considered as fully **Depreciated**. Ten percent **Defects** is equal to one percent **Damage**.

The concept of **Defects** and **Damage** is very easily understood and applied as compared to the more traditional subjective ratings of Excellent, Good, Fair or Poor. Consequently, the information resulting from bridge inspections is an order of magnitude more reliable and accurate.

Understanding the Inspection Forms

Inspection reports are headed **Bridge Inspection Report or Culvert Inspection Report**. In the top-right of each form is a general arrangement photograph of the structure taken on the day of inspection.

In the top-left box is basic tombstone data as follows:

- Name of the bridge in large bold font
- The type of bridge or culvert



- The road the structure is on
- Name of the Owner
- Structure Location Information
- The Owner specified Structure Identification Number (Site ID)
- District
- Year of original construction per legacy information.
- Length of the Bridge per legacy information
- Width of the Structure per legacy information
- Number of spans
- The span arrangement is shown in metres for bridges only.

In the next box down is recorded the date of inspection, principal inspector, assistant inspector, the weather for the entire day, and the approximate temperature range on the day of inspection.

In the small box under the General Arrangement photograph is shown the AADT per legacy information, (or updated as the case may be), the number of available traffic lanes crossing the structure, the structure skew angle in degrees, and the general direction of the road that crosses the structure, for example E-W means East to West. Accompanying this information are the Latitude and Longitude at the centre of the structure expressed in decimal degrees. Also include is data where applicable or available for the road width, percent trucks, and any load posting.

The Component Inspection Information is recorded next. The number of components varies based on the complexity of the structure. In the left column for each component is listed:

- Component name in bold with the component count in parenthesis.
- The general category for the component in *Italics*.
- The Length, Width, Diameter, & Height of the component in metres based on legacy information, or field measure, and as appropriate.

Please note that measurements for substructure items are approximate only.

The second column of the Component Inspection Information captures the actual field inspection information for each component. Information is generally recorded on an exception basis. If there are no annotations it can be safely assumed that the component is generally in satisfactory condition for its age. The following sub-headings explain in detail the inspection information:

Defects

Defects are relatively benign changes to a bridge component that cannot be attributed to simple aging. They result from a material Defect or lack of required maintenance. The



amount of Defects is estimated to the nearest five percent based on visual inspection of all similar components included in the component count. For example, bridges have typically four wing walls, so the estimated defects are applied over all four wing walls. The Defects are characterized with a qualifying comment that is computer generated from drop-down lists in the Keystone Bridge Management System. Where Defects exceed 10% they are highlighted in Yellow.

Damage

Damage is any change to a structure that alters its structural form, strength, or function. Damage may result from untended Defects. The Damage is estimated and reported analogous to Defects, except a level of accuracy of plus or minus 2% or better is maintained. Where Damage equals 5% to 10% it is highlighted in Amber. When Damage is equal to or greater than 10% it is highlighted in Red.

Red and amber flags appear to the right if damage is considered as critical or major respectively. This way an otherwise small amount of damage is brought to attention if the severity warrants it.

Maintenance

Maintenance recommendations are selected from a component specific drop-down menu in the Keystone Bridge Management System. Up to two maintenance recommendations can be selected and reported.

Capital Recommendation

Capital Recommendations are selected from a list of three options; Do Nothing, Repair, or Replace. The number of years in the future the Capital investment should take place is based on the inspector's best judgement, without considering the optimal timing for a comprehensive rehabilitation or replacement.

Performance

If a component has a functional impairment, this may be noted in the Performance comment. The Performance comment is created through a context sensitive drop-down menu. The performance comment only appears when a performance defect has been identified.

Note

Where the above categories are insufficient to capture the inspection information, Keystone adds an unlimited comment at the bottom of the second column.



Capital Needs Cost Estimate Breakdown

At the end of each Inspection Report is a section titled as per the above.

Capital costs estimates are automatically generated by the Keystone Bridge Management System for standard items which include:

- Deck Replacement
- Deck Concrete Overlay (O'Lay)
- Barrier Wall Replacement (B/Wall)
- Waterproof & Pave (WP&P)
- Expansion Joint (X-Jnt)

Unit prices for the above work are based on MTO and client supplied data and extensions are based on geometric data residing in the KBMS database. The unit costs are indicated on the form.

The Contract Administration & Contingencies is a straight 20% mark-up. The Estimated Traffic Management & Civil Items is usually included and is based on experience and the nature of the capital work.

Recommendations for additional investigations are included on the same page as the Capital Needs. A summary comment regarding the structure is included under the Inspection Comments heading.

At the bottom of the last page of each inspection report the BCI number, Straight-Line Depreciation percentage and Parabolic Depreciation percentage is expressed.

Inspection Images

All of the photographs taken at the time of inspection are displayed six per page in the section immediately following the Inspection Report. The Image Number is displayed in the top-left corner of each photo. A brief caption is provided below each photo. For a more detailed look at a photo, the original images are available upon request for a period of two years after the inspection.

Digital Copy

This entire report is reproduced in PDF format on a DVD disc shipped with this report. Individual inspection reports are included in their own folder together with reduced images.



Limitations

Keystone Bridge Management Corp. endeavours to provide valuable bridge asset management services that help its clients to prioritize and fund their bridge and large culvert capital and maintenance needs. Furthermore we advise of structural performance deficiencies and attendant risks. In short, we help our clients sustain the life of their road structure inventory commensurate with economic and risk management considerations.

Keystone provides these services in a fiercely competitive business environment. Our business value in terms of completing a routine biennial bridge inspection is to provide a competent highly experienced lead inspector and a student assistant. Our explicit attitude for the field work is “it takes as long as it takes.” The Client needs to understand however the following caveats with respect to the reporting provided herein:

1. Field measurements are only to an accuracy that reasonably supports depreciation modelling of the structure and should not be relied upon for any other purpose.
2. The inspection is mostly visual in nature and thus components of the structure that are not reasonably accessible due to depth of water, height, and the like will have a compromised assessment.
3. Ambient lighting and debris can hide or disguise defects and damage.
4. Heavy traffic will preclude a thorough inspection of deck surfaces.
5. Latent defects are not normally discoverable in a routine inspection.
6. There will always be inherent subjectivity when assessing defects and damage.
7. Cost estimates are based on average historical information and are not necessarily current or suitable for local conditions.
8. Where in our opinion the conventional visual inspection is insufficient to adequately and responsibly assess the structure we will recommend follow-up investigations such as boat or ice access inspections, bridge deck condition surveys, and other enhanced inspection methods.



Closing

Keystone Bridge Management Corp. is pleased to report on the condition of the Town of Gananoque vehicle and pedestrian bridges. Should there be any lingering concerns or additional information required with respect to this assignment, then Keystone will be happy to respond.

We trust the services rendered are complete, and in full keeping with the Terms of Reference. It is Keystone's sincerest desire that the recommendations stemming from this work will be helpful to the Town of Gananoque in keeping their structural inventory, safe, sound, serviceable, and sustainable. Keystone strives to help you get the most out of your road structure assets.

Harold Kleywegt, P.Eng.
Managing Director
Keystone Bridge Management Corp.



Bridge Inspection Report

Black (Snappers) Bridge

Truss-Pony	Site ID	1
Gananoque Waterfront Trail	District	
Town of Gananoque	Built	1924
Gananoque River	Length	36 m
Gananoque Waterfront Trail 400m north of Nalon Rd.	Width	6.2 m
	Spans	1
Span Arrangement (m's)	36	
Feature Under	Water	



Insp Date	May 5, 2016
Inspector	John Landry, EIT
Assistant	Steve Reid, C.E.T.
Weather	Mostly Over Cast with some Sunny Periods
Low/High	10 °c 17 °c

AADT	0	Latitude	44.33887200
Lanes	0	Longitude	-76.17497200
Skew	0 °	Orient	N-S
Speed	0 km/h	Road Width	
Truck		Load Posting	

Component Inspection Information

Timber Wear Surface (1)	Defects	0.0%	
Wear Surface	Damage	0.0%	
Length:	36 m	Maintenance	None
Width:	1 m	Capital Rec.	None
Height:		<i>Plank on tie wear surface is in good overall condition. Little change 2016.</i>	

Timber Post Timber Rail (2)	Defects	0.0%	
Railings	Damage	0.0%	
Length:	36 m	Maintenance	None
Width:		Capital Rec.	None
Height:	1.5 m	<i>Railings are secure and in good condition.</i>	

Diagonal/Post/Hangar (20)	Defects	0.0%	
Diagonals	Damage	0.0%	
Length:		Maintenance	Remove debris
Width:	0.24 m	Capital Rec.	None
Height:		<i>Debris collected at bottom chord gussets.</i>	



Component Inspection Information

Diagonal/Post/Hangar (10)		Defects 0.0%	
Hangars		Damage 0.0%	
Length:		Maintenance Remove debris	
Width:	0.24 m	Capital Rec. None	
Height:	3.5 m	<i>Debris collected at gussets at bottom chord.</i>	
Half Through or Pony (2)		Defects 0.0%	
Bottom Chord		Damage 0.0%	
Length:	36 m	Maintenance Remove debris	Partial Inspection
Width:		Capital Rec. None	
Height:	0.48 m	<i>Good condition except for debris at gusset locations.</i>	
Half Through or Pony (2)		Defects 0.0%	
Top Chord		Damage 0.0%	
Length:	36 m	Maintenance None	
Width:		Capital Rec. None	
Height:	0.48 m	<i>Good condition given age.</i>	
Steel Floor Beam (7)		Defects 2.0%	Minor Corrosion
Floor Beams		Damage 0.0%	
Length:	5.8 m	Maintenance None	Partial Inspection
Width:		Capital Rec. None	
Height:	0.84 m	<i>Floor beams appear to be in good condition. Could not be fully inspected 2016.</i>	
Stringers (24)		Defects 2.0%	Minor Corrosion
Stringers		Damage 0.0%	
Length:	5.8 m	Maintenance None	Partial Inspection
Width:		Capital Rec. None	
Height:	0.51 m	<i>Stringers appear to be in good condition. Minor loss of coating.</i>	
RC Abutment Wall (2)		Defects 40.0%	Moderate AAR Cracking, Minor Leaching/Seepage, Moderate Graffiti
Abutment Stem		Damage 4.0%	Minor Disintegration, Minor Delamination
Length:	7.35 m	Maintenance None	
Width:		Capital Rec. None	
Height:	3.75 m	<i>Age related deterioration. Disintegration encroaching on south bearings, most notably the SE corner.</i>	



Component Inspection Information

RC Ballast Wall (2) Ballast Wall Length: 7.35 m Width: Height: 1.05 m	Defects	2.0%	Minor AAR Cracking	
	Damage	0.0%		
	Maintenance	Repair	Damage	Partial Inspection
	Capital Rec.	None		
			<i>Timber blocking at both deck ends is decayed and requires replacement as a maintenance item.</i>	
RC Wing Walls (4) Wing Walls Length: 4.2 m Width: Height: 3.15 m	Defects	40.0%	Moderate AAR Cracking, Minor Leaching/Seepage	
	Damage	1.0%	Moderate Disintegration, Minor Delamination	
	Maintenance	None		
	Capital Rec.	None		
			<i>Similar condition as abutments.</i>	
Steel Sliding Plate (4) Abutment Bearings Length: Width: Height:	Defects	0.0%		
	Damage	0.0%		
	Maintenance	Remove debris		
	Capital Rec.	None		
			<i>Debris around bearings should be removed. Disintegration of abutment wall encroaching on bearings.</i>	
Water Channel (1) Channel	Defects	0.0%		
	Damage	0.0%		
	Maintenance	None		
	Capital Rec.	None		
			<i>No concerns.</i>	
Embankment (2) Embankment	Defects	10.0%	Moderate Erosion	
	Damage	0.0%		
	Maintenance	Slope revetment		
	Capital Rec.	None		Perf Def: Over-steepened
			<i>Southeast timber retaining wall has failed. Excessive erosion should be repaired. Timber retaining wall in other corners beginning to deteriorate.</i>	
Delineator (4) Signs Length: Width: Height:	Defects	0.0%		
	Damage	0.0%		
	Maintenance	Replace Sign		
	Capital Rec.	None		
			<i>Missing one delineator in SW corner.</i>	



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	✗	m ²	0.0	\$300	\$0
<i>Deck Concrete Overlay</i>	✗	m ²	223.2	\$350	\$0
<i>Deck Replacement</i>	✗	m ²	223.2	\$2,000	\$0
<i>Barrier Wall Replacement</i>	✗	m	60.0	\$1,500	\$0
<i>Expansion Joint</i>	✗	m	12.4	\$3,000	\$0
<i>Waterproof & Pave</i>	✗	m ²	80.0	\$100	\$0
<i>Bearing Replacement</i>	✗	Count	0.0	\$5,000	\$0
<i>Approach Guiderail</i>	✗	m	80.0	\$200	\$0

Other Work

Retaining Walls \$40,000

Structural Items Subtotal \$40,000

Mobilization General Sitework 10% \$10,000

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$10,000

Total Rehabilitation Cost Estimate \$60,000

<i>Rec'd Investigations</i>	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	✗	✗	✗	✗	✓	✗	✗	✗

Recommended Capital Work Summary

Recommended Capital Year 2017

Retaining Walls

Inspection Comments

Thorough cleaning of bottom chord of truss and bearing seat required. Plan for replacing timber retaining walls in all four corners. Replace timber blocking at both ballast walls.

Bridge Condition Index: 59.6 Parabolic Depreciation: 5.8 % Straight Line Depreciation: 4.1 %

Estimated Replacement Value: \$2,114,000

Estimated Remaining Service Life: 28 Years



Image 85



East elevation

Image 81



South approach

Image 82



North approach

Image 83



Upstream channel west

Image 84



Downstream channel east

Image 86



Typ deck



Image 87



West truss

Image 88



Rotted timber south end

Image 89



Typical panel point debris

Image 90



East truss

Image 91



Rotted timber north ballast

Image 92



Typical rust on northeast diagonal



Image 93



Erosion southeast corner

Image 94



Southeast wing wall

Image 95



Soffit

Image 96



North abutment wall

Image 97



South abutment wall

Image 98



Delamination at southeast bearing





Bridge Inspection Report

Wood Bridge

Timber Beam	Site ID	2
Gananoque Waterfront Trail	District	
Town of Gananoque	Built	2004
Ditch	Length	5.8 m
Gananoque Waterfront Trail 250m north of Nalon Rd	Width	1.22 m
	Spans	1
Span Arrangement (m's)		5.8
Feature Under		Water



Insp Date	May 5, 2016
Inspector	John Landry, EIT
Assistant	Steve Reid, C.E.T.
Weather	Mostly Over Cast with some Sunny Periods
Low/High	10 °c 17 °c

AADT	0	Latitude	44.33768100
Lanes	0	Longitude	-76.17521700
Skew	0 °	Orient	E-W
Speed	0 km/h	Road Width	
Truck		Load Posting	

Component Inspection Information

Timber-Sawn (1)	Defects	0.0%	
Deck Surface	Damage	0.0%	
Length:	5.8 m	Maintenance	None
Width:	1.22 m	Capital Rec.	None
Height:			<i>Secure, no concerns.</i>

Timber Post Timber Rail (2)	Defects	0.0%	
Railings	Damage	0.0%	
Length:	5.8 m	Maintenance	None
Width:		Capital Rec.	None
Height:	1.1 m		<i>Secure, no concerns.</i>

Treated Sawn Timber (2)	Defects	0.0%	
Girders	Damage	0.0%	
Length:	5.8 m	Maintenance	None
Width:	0.25 m	Capital Rec.	None
Height:	0.25 m		<i>Girders are presumed cedar logs and are in reasonable condition.</i>



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	X	m ²	0.0	\$300	\$0
<i>Deck Concrete Overlay</i>	X	m ²	7.1	\$350	\$0
<i>Deck Replacement</i>	X	m ²	7.1	\$2,000	\$0
<i>Barrier Wall Replacement</i>	X	m	29.8	\$1,500	\$0
<i>Expansion Joint</i>	X	m	2.4	\$3,000	\$0
<i>Waterproof & Pave</i>	X	m ²	80.0	\$100	\$0
<i>Bearing Replacement</i>	X	Count	4.0	\$5,000	\$0
<i>Approach Guiderail</i>	X	m	80.0	\$200	\$0

Other Work

\$0

Structural Items Subtotal \$0

Mobilization General Sitework 10% \$0

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$0

Total Rehabilitation Cost Estimate \$0

<i>Rec'd Investigations</i>	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	X	X	X	X	X	X	X	X

Recommended Capital Work Summary

Recommended Capital Year 0

Inspection Comments

No concerns. Little change in 2016.

Bridge Condition Index: 85.0 Parabolic Depreciation: 86.7 % Straight Line Depreciation: 63.9 %

Estimated Replacement Value: \$87,000

Estimated Remaining Service Life: 15 Years



Image 101



South elevation

Image 99



West approach

Image 100



East approach

Image 102



Typical deck

Image 103




Typical soffit

Image 104



Typical abutment and bearing





Bridge Inspection Report

Hudson Bridge

Truss-Through	Site ID	3
Machar St	District	
Town of Gananoque	Built	1911
Gananoque River	Length	39.1 m
Machar St. 100m east of River St.	Width	5.2 m
	Spans	1
Span Arrangement (m's) 39.1		
Feature Under Water		



Insp Date **May 5, 2016**
 Inspector **John Landry, EIT**
 Assistant **Steve Reid, C.E.T.**
 Weather **Mostly Over Cast with some Sunny Periods**
 Low/High **10 °c 17 °c**

AADT	0	Latitude	44.33072800
Lanes	1	Longitude	-76.16758100
Skew	0 °	Orient	E-W
Speed	50 km/h	Road Width	
Truck		Load Posting	

Component Inspection Information

Timber-Laminated (1)

Deck Surface

Length: **39.1 m**
 Width: **3.9 m**
 Height:

Defects **20.0%** Moderate Checking
 Damage **30.0%** Moderate Wear, Major Wear
 Maintenance **Local repair**
 Capital Rec. **Replace in 1 year**

Timber has major rutting, allowing screws and steel spacers to protrude through deck. Recommend placing asphalt padding until deck can be replaced.

Soffit (1)

Deck Soffit

Length: **39.1 m**
 Width: **4 m**
 Height:

Defects **0.0%**
 Damage **0.0%**
 Maintenance **None**
 Capital Rec. **None**

Partial Inspection

Laminated timber on steel tie deck. Lack of waterproofing is allowing water to reach steel stringers below deck surface.

Thrie Beam G/R (2)

Railings

Length: **39.1 m**
 Width:
 Height: **0.7 m**

Defects **0.0%**
 Damage **1.0%** Minor Impact
 Maintenance **None**
 Capital Rec. **None**

Good condition, secure. Approach guiderail in NE corner has impact damage.



Component Inspection Information

Bottom Chord (2)	Defects 100.0% Moderate Corrosion	
Bottom Chord	Damage 0.0%	
Length: 39.1 m	Maintenance None	
Width:	Capital Rec. None	
Height: 0.1 m	<i>Eye bars have uniform tension. Reasonable condition given age. One eye bar in SE corner damaged (bent) from handling.</i>	
Diagonal/Post/Hangar (4)	Defects 100.0% Moderate Corrosion	
Diagonals/Hangars	Damage 0.0%	
Length: 0.25 m	Maintenance None	
Width: 0.2 m	Capital Rec. None	Perf Def: Connection
Height:	<i>Load test completed in 2014. Under loading all hangars receive tension.</i>	
Through (2)	Defects 95.0% Moderate Corrosion, Major Corrosion	
Top Chord	Damage 5.0% Moderate Perforation	
Length: 39.1 m	Maintenance None	Partial Inspection
Width: 4.5 m	Capital Rec. None	
Height: 2.5 m	<i>Perforations located in web and top flange of end diagonals.</i>	
Through (2)	Defects 0.0%	
Portal	Damage 0.0%	
Length:	Maintenance None	
Width:	Capital Rec. None	
Height:	<i>Good.</i>	
Steel Floor Beam (6)	Defects 95.0% Moderate Corrosion	
Floor Beams	Damage 5.0% Minor Perforation, Moderate Section Loss	
Length: 5 m	Maintenance None	Partial Inspection
Width:	Capital Rec. None	
Height: 0.69 m	<i>Perforations noted on two west most floor beams. A boat inspection is recommended to review condition of all floor beams from close up.</i>	
Steel Floor Beam (49)	Defects 5.0% Minor Corrosion	
Steel Deck Ties	Damage 0.0%	
Length: 6.5 m	Maintenance None	Partial Inspection
Width:	Capital Rec. None	
Height: 0.27 m	<i>These members are part of the deck system and a retrofit to the bridge. No concerns noted.</i>	



Component Inspection Information

Stringers (3) Stringers Length: 39.1 m Width: Height: 0.6 m	Defects 10.0%	Moderate Corrosion	
	Damage 0.0%		
	Maintenance None		Partial Inspection
	Capital Rec. None		
	<i>These are not original to the bridge. corrosion caused by lack of waterproofing on deck.</i>		
RC Abutment Wall (2) Abutment Stem Length: 5 m Width: 0.2 m Height: 1.4 m	Defects 5.0%	Minor Leaching cracks, Minor Scaling	
	Damage 0.0%		
	Maintenance None		
	Capital Rec. None		
	<i>Abutments have light scaling and leaching cracks.</i>		
RC Ballast Wall (2) Ballast Wall Length: 5 m Width: Height: 1 m	Defects 0.0%		
	Damage 0.0%		
	Maintenance None		Partial Inspection
	Capital Rec. None		
	<i>No concerns.</i>		
Steel Sliding Plate (4) Abutment Bearings Length: Width: Height:	Defects 90.0%	Moderate Corrosion	
	Damage 10.0%	Moderate Section Loss	
	Maintenance Power Wash		
	Capital Rec. None		Perf Def: Seizing
	<i>Severely corroded. Debris around bearings is increasing rate of corrosion in bearings and end Diagonals.</i>		
Water Channel (1) Channel	Defects 0.0%		
	Damage 0.0%		
	Maintenance None		
	Capital Rec. None		
	<i>Deep channel with current.</i>		
Embankment (2) Embankment	Defects 0.0%		
	Damage 0.0%		
	Maintenance None		
	Capital Rec. None		
	<i>Well vegetated.</i>		



Component Inspection Information

Delineator (4)	Defects 0.0%
Signs	Damage 0.0%
Length:	Maintenance None
Width:	Capital Rec. None
Height:	In place. Cautionary load posting sign in place at both ends.



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
Misc Concrete Repairs	X	m ²	0.0	\$300	\$0
Deck Concrete Overlay	X	m ²	203.3	\$350	\$0
Deck Replacement	X	m ²	203.3	\$2,000	\$0
Barrier Wall Replacement	X	m	63.1	\$1,500	\$0
Expansion Joint	X	m	10.4	\$3,000	\$0
Waterproof & Pave	X	m ²	80.0	\$100	\$0
Bearing Replacement	X	Count	0.0	\$5,000	\$0
Approach Guiderail	X	m	80.0	\$200	\$0

Other Work

Replace \$3,000,000

Structural Items Subtotal \$3,000,000

Mobilization General Sitework 10% \$300,000

Estimated Traffic Management & Civil Items \$10,000

Contract Admin & Contingencies 20% \$662,000

Total Rehabilitation Cost Estimate \$3,972,000

Rec'd Investigations	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	X	X	X	X	✓	✓	✓	✓

Recommended Capital Work Summary

Recommended Capital Year 2020

Replace

Inspection Comments

The floor system and end diagonals are corrosion perforated and can not be cost effectively repaired. Bridge requires black and white legal load posting signs with a supporting load limit bylaw. Immediate cleaning of bottom chords required. Further investigation and documentation recommended. Without major repairs it will probably be necessary to close the bridge to traffic in about eight years.

Bridge Condition Index: 62.7 Parabolic Depreciation: 33.4 % Straight Line Depreciation: 21.8 %

Estimated Replacement Value: \$2,401,000

Estimated Remaining Service Life: 5 Years



Image 114



North elevation

Image 105



East approach

Image 106



West approach

Image 107



South elevation

Image 108



West floor beam perforation

Image 109



West abutment wall



Image 110



Typical soffit

Image 111



West deck end

Image 112



Pitted truss northwest end diagonal

Image 113



Perforated truss northwest end diagonal

Image 115



Screws protruding through deck

Image 116



Perforated web in northeast diagonal



Image 117



East deck end

Image 118



Typical deck

Image 119



East abutment wall

Image 120



Perforated web in southeast diagonal

Image 121



East soffit view

Image 122




Downstream channel



Image 123



Northeast guardrail





Bridge Inspection Report

Rail to Trail Bridge

Timber Beam	Site ID	4
Gananoque Waterfront Trail	District	
Town of Gananoque	Built	1920
Gananoque River	Length	31.6 m
Gananoque Waterfront Trail 150m east of River St	Width	1.8 m
	Spans	3
Span Arrangement (m's) 10.1,9.5,10.1		
Feature Under Water		



Insp Date	May 5, 2016
Inspector	John Landry, EIT
Assistant	Steve Reid, C.E.T.
Weather	Mostly Over Cast with some Sunny Periods
Low/High	10 °c 17 °c

AADT	0	Latitude	44.32848600
Lanes	0	Longitude	-76.16688900
Skew	0 °	Orient	E-W
Speed	0 km/h	Road Width	
Truck		Load Posting	

Component Inspection Information

Timber-Sawn (1)

Deck Surface

Length: 31.6 m
Width: 4 m
Height: 0.2 m

Defects 0.0%

Damage 30.0% Major Decay, Moderate Decay

Maintenance None

Capital Rec. Replace in 1 year

Timber 8" x 8" railroad ties display severe decay.

Timber Wear Surface (1)

Wear Surface

Length: 31.6 m
Width: 1.8 m
Height:

Defects 0.0%

Damage 5.0% Minor Wear

Maintenance None

Capital Rec. Replace in 1 year

Some damage down middle from unknown source. Old railroad ties are decaying and supporting vegetation growth.

Wood Post Wood Rail (2)

Barrier

Length: 31.6 m
Width:
Height: 1.4 m

Defects 0.0%

Damage 5.0% Moderate Decay

Maintenance Replace Bracing

Capital Rec. None

Cleats supporting rakers exhibit decay and require spot replacement. Railing system is secure.



Component Inspection Information

Steel-Rolled (6)	Defects 88.0% Moderate Corrosion	Partial Inspection
Girders	Damage 12.0% Critical Section Loss, Critical Perforation	
Length: 31.6 m	Maintenance None	
Width:	Capital Rec. Repair in 1 year	
Height: 0.6 m	<i>The girder ends at the abutments and piers are severely corroded with perforations and web crippling. See images.</i>	
RC Abutment Wall (2)	Defects 2.0% Minor Scaling, Minor Leaching/Seepage	Partial Inspection
Abutment Stem	Damage 0.0%	
Length: 3.9 m	Maintenance None	
Width:	Capital Rec. None	
Height: 2 m	<i>No concerns.</i>	
RC Shaft (2)	Defects 2.0% Minor Scaling, Minor Leaching/Seepage	Partial Inspection
Pier Column/Shaft	Damage 0.0%	
Length: 3.9 m	Maintenance None	
Width:	Capital Rec. None	
Height: 3 m	<i>No Concerns.</i>	
Water Channel (1)	Defects 0.0%	
Channel	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Deep channel with current.</i>	
Embankment (2)	Defects 5.0% Moderate Erosion	
Embankment	Damage 0.0%	
	Maintenance Slope revetment	
	Capital Rec. None	
	<i>Stable, groomed, with some local erosion. An old timber retaining wall in NW quadrant has failed.</i>	



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
Misc Concrete Repairs	X	m ²	0.0	\$300	\$0
Deck Concrete Overlay	X	m ²	56.9	\$350	\$0
Deck Replacement	X	m ²	56.9	\$2,000	\$0
Barrier Wall Replacement	X	m	55.6	\$1,500	\$0
Expansion Joint	X	m	3.6	\$3,000	\$0
Waterproof & Pave	X	m ²	80.0	\$100	\$0
Bearing Replacement	X	Count	0.0	\$5,000	\$0
Approach Guiderail	X	m	80.0	\$200	\$0

Other Work

Replace \$500,000

Structural Items Subtotal \$500,000

Mobilization General Sitework 10% \$50,000

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$110,000

Total Rehabilitation Cost Estimate \$660,000

Rec'd Investigations	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	X	✓	X	X	✓	✓	✓	X

Recommended Capital Work Summary

Recommended Capital Year 2017

Replace

Inspection Comments

Bridge girders are severely corroded at ends and may settle or fail with little warning. Ties are increasingly decayed. Highly recommend a more thorough review with a boat inspection in order to assure continued public safety. Should consider closing this bridge for public use by 2020.

Bridge Condition Index: 50.6 Parabolic Depreciation: 2.0 % Straight Line Depreciation: 0.9 %

Estimated Replacement Value: \$699,000

Estimated Remaining Service Life: 4 Years



Image 140



North elevation

Image 124



West approach

Image 125



East approach

Image 126



Upstream channel north

Image 127



Downstream channel south

Image 128



Typical deck



Image 129



Northeast girder end

Image 130



East soffit

Image 131



North face of east pier

Image 132



Typical rotted tie

Image 133



Perforated girder on west pier

Image 134



West girder end





Typical pier



West abutment wall



East girder ends at abutment wall



South face of west pier girders



Southeast retaining wall



Northwest embankments



Bridge Inspection Report

Power Canal Ped Bridge

Slab on Steel Girder	Site ID	5
Gananoque Waterfront Trail	District	
Town of Gananoque	Built	2015
Intake Channel	Length	9 m
Gananoque Waterfront Trail 30m south of Park St	Width	2.1 m
	Spans	1
Span Arrangement (m's) 1 @ 9		
Feature Under	Water	



Insp Date	May 5, 2016
Inspector	John Landry, EIT
Assistant	Steve Reid, C.E.T.
Weather	Mostly Over Cast with some Sunny Periods
Low/High	10 °c 17 °c

AADT	0	Latitude	44.32806700
Lanes	0	Longitude	-76.16583300
Skew	0 °	Orient	N-S
Speed	0 km/h	Road Width	
Truck		Load Posting	

Component Inspection Information

Concrete Wear Surface (1)	Defects	0.0%	Checking
Wear Surface	Damage	0.0%	
Length:	9.4 m	Maintenance	None
Width:	1.7 m	Capital Rec.	None
Height:	0.8 m		<i>New 2015.</i>

Square Tube Rail & Post (2)	Defects	10.0%	Minor Corrosion, Minor Tarnishing
Barrier	Damage	0.0%	
Length:	9.4 m	Maintenance	None
Width:		Capital Rec.	None
Height:	1.1 m		<i>Pedestrian barrier recycled from previous design.</i>

Steel-Rolled (2)	Defects	0.0%	
Girders	Damage	0.0%	
Length:	9 m	Maintenance	None
Width:		Capital Rec.	None
Height:	0.3 m		<i>New steel girders installed in 2015.</i>



Component Inspection Information

CIP RC Slope Paving (2)	Defects 0.0%	
Channel Lining	Damage 0.0%	
	Maintenance None	Partial Inspection
	Capital Rec. None	
	<i>This refers to bridge supports. No concerns.</i>	

Water Channel (1)	Defects 0.0%	
Channel	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Power canal. Swift water and exceptionally high at time of inspection.</i>	

Embankment (2)	Defects 0.0%	
Embankment	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Groomed city park.</i>	



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	X	m ²	0.0	\$300	\$0
<i>Deck Concrete Overlay</i>	X	m ²	18.9	\$350	\$0
<i>Deck Replacement</i>	X	m ²	18.9	\$2,000	\$0
<i>Barrier Wall Replacement</i>	X	m	33.0	\$1,500	\$0
<i>Expansion Joint</i>	X	m	4.2	\$3,000	\$0
<i>Waterproof & Pave</i>	X	m ²	80.0	\$100	\$0
<i>Bearing Replacement</i>	X	Count	4.0	\$5,000	\$0
<i>Approach Guiderail</i>	X	m	80.0	\$200	\$0

Other Work

\$0

Structural Items Subtotal \$0

Mobilization General Sitework 10% \$0

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$0

Total Rehabilitation Cost Estimate \$0

<i>Rec'd Investigations</i>	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	X	X	X	X	X	X	X	X

Recommended Capital Work Summary

Recommended Capital Year

Inspection Comments

Structure replaced in 2015. No concerns.

Bridge Condition Index: 81.4 Parabolic Depreciation: 72.5 % Straight Line Depreciation: 53.9 %

Estimated Replacement Value: \$96,000

Estimated Remaining Service Life: 60 Years



Image 148



East elevation

Image 143



North approach

Image 144



South approach

Image 145



Upstream channel west

Image 146



Downstream channel east

Image 147



Typical deck





West elevation




Bent railing segment



Typical soffit



Typical railing





Bridge Inspection Report

King Street Bridge

Slab on Steel Girder	Site ID	6
King St. East	District	
Town of Gananoque	Built	1930
Gananoque River	Length	51.1 m
King St. East 120m south of Park St.	Width	13.2 m
	Spans	1
Span Arrangement (m's) 16.8, 17.6, 16.8		
Feature Under	Water	



Insp Date	May 5, 2016	
Inspector	John Landry, EIT	
Assistant	Steve Reid, C.E.T.	
Weather	Mostly Over Cast with some Sunny Periods	
Low/High	10 °c	17 °c

AADT	0	Latitude	44.32703300
Lanes	2	Longitude	-76.16455600
Skew	0 °	Orient	N-S
Speed	50 km/h	Road Width	
Truck		Load Posting	

Component Inspection Information

Protected ECRC Deck (1)	Defects	0.0%
Deck Surface	Damage	0.0%
Length: 53 m	Maintenance	None
Width: 13.2 m	Capital Rec.	None
Height:	<i>See wearing surface.</i>	

Soffit (1)	Defects	0.0%	
Deck Soffit	Damage	0.0%	
Length: 51.1 m	Maintenance	None	Partial Inspection
Width: 13.2 m	Capital Rec.	None	
Height:	<i>Good condition, some paint over-spray. Little Change 2016.</i>		

Concrete Wear Surface (1)	Defects	0.0%	
Wear Surface	Damage	0.0%	
Length: 51.1 m	Maintenance	None	
Width: 9.1 m	Capital Rec.	None	Perf Def: Polished
Height:	<i>Tinning has been worn away along wheel paths. Polishing occurring.</i>		



Component Inspection Information

X- Joint Conventional (4)		Defects 0.0%	
Expansion Joints		Damage 0.0%	
Length:	13.2 m	Maintenance Remove Debris	
Width:		Capital Rec. None	
Height:		Good condition. Silty debris in seal.	
Sidewalk (2)		Defects 2.0%	Minor Pop-outs, Minor Abrasion
Sidewalks		Damage 0.0%	
Length:	51.1 m	Maintenance None	
Width:	1.7 m	Capital Rec. None	
Height:		No concerns.	
Open Parapet-Decorative (2)		Defects 5.0%	Insignificant AAR Cracking
Barrier		Damage 0.0%	
Length:	60 m	Maintenance None	
Width:		Capital Rec. None	
Height:	1.1 m	Some faint AAR present.	
Steel-Rolled (10)		Defects 1.0%	Minor Corrosion
Girders		Damage 0.0%	
Length:	51.1 m	Maintenance None	
Width:		Capital Rec. None	
Height:	0.78 m	Girders coated during 2006 rehab. Some edge rust has reappeared.	
RC Abutment Wall (2)		Defects 20.0%	Moderate Scaling, Moderate Shallow Patches
Abutment Stem		Damage 1.0%	Moderate Delamination
Length:		Maintenance None	
Width:	14.75 m	Capital Rec. None	
Height:	5 m	Scaling occurring around water line.	
RC Ballast Wall (2)		Defects 0.0%	
Ballast Wall		Damage 0.0%	
Length:		Maintenance None	Not Inspected
Width:	14.75 m	Capital Rec. None	
Height:	1 m	Not accessible.	



Component Inspection Information

RC Wing Walls (4) <i>Wing Walls</i> Length: Width: Height:	Defects 20.0% Moderate Scaling Damage 0.0% Maintenance None Capital Rec. None <i>No concerns.</i>	Partial Inspection
RC Shaft (2) <i>Pier Column/Shaft</i> Length: Width: 14.75 m Height: 5 m	Defects 25.0% Moderate Scaling, Moderate Shallow Patches Damage 2.0% Moderate Disintegration, Minor Delamination Maintenance None Capital Rec. None <i>Pockets of delamination occurring on piers.</i>	
Laminated Rubber Brg (40) <i>Pier Bearings</i> Length: Width: Height:	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Not accessible during inspection. Appear to be in good condition.</i>	Not Inspected
Laminated Rubber Brg (20) <i>Abutment Bearings</i> Length: Width: Height:	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>No concerns noted.</i>	Partial Inspection
Water Channel (1) <i>Channel</i>	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Channel low at time of inspection.</i>	
Embankment (2) <i>Embankment</i>	Defects 0.0% Damage 0.0% Maintenance None Capital Rec. None <i>Groomed.</i>	



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	X	m ²	0.0	\$300	\$0
<i>Deck Concrete Overlay</i>	X	m ²	674.5	\$350	\$0
<i>Deck Replacement</i>	X	m ²	674.5	\$2,000	\$0
<i>Barrier Wall Replacement</i>	X	m	75.1	\$1,500	\$0
<i>Expansion Joint</i>	X	m	26.4	\$3,000	\$0
<i>Waterproof & Pave</i>	X	m ²	80.0	\$100	\$0
<i>Bearing Replacement</i>	X	Count	20.0	\$5,000	\$0
<i>Approach Guiderail</i>	X	m	80.0	\$200	\$0

Other Work

\$0

Structural Items Subtotal \$0

Mobilization General Sitework 10% \$0

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$0

Total Rehabilitation Cost Estimate \$0

<i>Rec'd Investigations</i>	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	X	X	X	X	X	X	X	X

Recommended Capital Work Summary

Recommended Capital Year 0

Inspection Comments

Structure is in good condition.

Bridge Condition Index: 74.7 Parabolic Depreciation: 24.6 % Straight Line Depreciation: 18.5 %

Estimated Replacement Value: \$3,283,000

Estimated Remaining Service Life: 44 Years



Image 194



West elevation

Image 183



South approach

Image 184



South expansion joint

Image 185



South pier expansion joint

Image 186



Downstream channel east

Image 187



North pier expansion joint





North expansion joint



North approach



Plaques on northwest end



Typical deck



Upstream channel west



Typical sidewalk and railing




Image 195



South abutment wall

Image 196



South face of south pier

Image 197



South span soffit

Image 198



West face of south pier

Image 199



North face of south pier

Image 200



Centre span soffit



Image 201



South face of north pier

Image 202



North face north pier

Image 203



North abutment wall

Image 204



North span soffit

Image 205



Typical bearing

Image 207



East elevation



Bridge Inspection Report

King Street Pedestrian Bridge

Plate Girder-Half Through Site ID **7**
Gananoque Waterfront Trail District
Town of Gananoque Built **1927**
Gananoque Waterfront Trail Length **71.9 m**
Immediately downstream of Width **7.7 m**
King Street Spans **2**
Span Arrangement (m's) **35.4, 36.5**
Feature Under **Water**



Insp Date **May 5, 2016**
Inspector **John Landry, EIT**
Assistant **Steve Reid, C.E.T.**
Weather **Mostly Over Cast with some Sunny Periods**

Low/High **10 °c 17 °c**

AADT **0** Latitude **44.32715300**
Lanes **0** Longitude **-76.16421000**
Skew **0 °** Orient **N-S**
Speed **0 km/h** Road Width
Truck Load Posting

Component Inspection Information

Timber Wear Surface (1)

Defects **0.0%**

Wear Surface

Damage **2.0%** **Moderate Decay**

Length: **71.9 m**

Maintenance **Local repair**

Width: **7 m**

Capital Rec. **None**

Height:

Bridge deck has a number of decayed planks. Repair locally as a maintenance item. Structure experienced punch through failure at north end of north span. Hole from punch through covered by plywood sheets. Recommend limiting structure to pedestrians only. Wood stringers are expected to be starting to decay.

Steel-Fabricated (2)

Defects **50.0%** **Moderate Corrosion**

Girders

Damage **12.0%** **Moderate Section Loss**

Length: **71.9 m**

Maintenance **None**

Partial Inspection

Width:

Capital Rec. **None**

Height: **3 m**

Exterior faces of girders are 80 % loss of coating and showing rust. Interior surfaces above deck properly coated.



Component Inspection Information

Steel Floor Beam (0) <i>Floor Beams</i>	Defects 90.0% Major Corrosion	Partial Inspection
Length:	Damage 10.0% Critical Section Loss	
Width:	Maintenance None	
Height:	Capital Rec. None	
	<i>Not possible to assess full condition.</i>	
Stringers (2) <i>Stringers</i>	Defects 80.0% Moderate Corrosion	
Length: 71.9 m	Damage 10.0% Critical Perforation, Major Section Loss	
Width:	Maintenance None	
Height: 0.6 m	Capital Rec. Repair in 1 year	
	<i>The stringers at the east end of the bridge have very large perforated areas of the web. The stringers are correspondingly weakened.</i>	
RC Abutment Wall (2) <i>Abutment Stem</i>	Defects 50.0% Moderate Leaching/Seepage, Moderate AAR Cracking	
Length:	Damage 2.0% Moderate Disintegration	
Width: 7.7 m	Maintenance None	
Height: 2 m	Capital Rec. None	
	<i>Abutments have moderate leaching and AAR cracking.</i>	
Mass Concrete Pier (1) <i>Pier Column/Shaft</i>	Defects 0.0%	Not Inspected
Length: 9 m	Damage 10.0% Major Disintegration	
Width: 2.5 m	Maintenance None	
Height: 4 m	Capital Rec. None	
	<i>Not possible to inspect properly due to high water. MRC 2010 report indicates significant undercutting at base of pier.</i>	
Pot Bearing (8) <i>Abutment Bearings</i>	Defects 0.0%	
Length:	Damage 0.0%	
Width:	Maintenance None	
Height:	Capital Rec. None	
	<i>Appear to be functional. Certainly adequate for present use. No change 2016.</i>	
Water Channel (1) <i>Channel</i>	Defects 0.0%	
	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Rapids under bridge.</i>	



Component Inspection Information

Embankment (2)	Defects 0.0%
Embankment	Damage 0.0%
	Maintenance Remove Brush/Trees
	Capital Rec. None
	Extremely dirty under west span. Infilling is preventing good air circulation under west span.



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
Misc Concrete Repairs	X	m ²	0.0	\$300	\$0
Deck Concrete Overlay	X	m ²	553.6	\$350	\$0
Deck Replacement	X	m ²	553.6	\$2,000	\$0
Barrier Wall Replacement	X	m	95.9	\$1,500	\$0
Expansion Joint	X	m	15.4	\$3,000	\$0
Waterproof & Pave	X	m ²	80.0	\$100	\$0
Bearing Replacement	X	Count	8.0	\$5,000	\$0
Approach Guiderail	X	m	80.0	\$200	\$0

Other Work

Replace timber deck \$170,000

Structural Items Subtotal	\$170,000
Mobilization General Sitework 10%	\$17,000
Estimated Traffic Management & Civil Items	\$0
Contract Admin & Contingencies 20%	\$37,000
Total Rehabilitation Cost Estimate	\$224,000

Rec'd Investigations	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	X	✓	X	X	X	✓	X	✓

Recommended Capital Work Summary

Recommended Capital Year 2018

Replace timber deck

Inspection Comments

Underside of bridge is severely corroded and dirty. Not possible to inspect fully due to height. Advanced and severe corrosion of certain areas of the bridge means a very thorough arms reach inspection will be needed to fully gauge condition and remaining useful life as a pedestrian bridge. Deck should only be replaced if Town is committed to repairing the structural steel floor system. May need to consider closing and removing this bridge as the most economical long term solution. Bridge should be closed in the winter to stop application of de-icing salt.

Bridge Condition Index: 47.5 Parabolic Depreciation: 0.0 % Straight Line Depreciation: 0.0 %



Estimated Replacement Value: \$4,065,000

Estimated Remaining Service Life: 5 Years



West elevation



South approach



North approach



Typical deck



Upstream channel west



Downstream channel east




Image 168



Patched hole in deck

Image 170



North abutment wall

Image 171



Perforated West floor beam at north end

Image 172



North span soffit

Image 173



Perforated gusset plate on west side

Image 174



North face of pier



Image 175



Perforated gusset plate on west side worth of pier

Image 176



Typical decayed deck board

Image 177



South face of pier

Image 178



South span soffit

Image 179



South abutment wall

Image 180



Detached cross brace in south span



Image 181




Typical cross brace gusset plate

Image 182



Typical debris and corrosion on floor beam



Bridge Inspection Report

Water Street Swing Bridge

Plate Girder-Half Through Site ID **8**
Water Street District
Town of Gananoque Built **1894**
Gananoque River Length **36.8 m**
Adjacent St. Lawrence River Width **4 m**
Spans **1**

Span Arrangement (m's) **2 @ 18**

Feature Under **Navigable Channel**



Insp Date **May 5, 2016**
Inspector **John Landry, EIT**
Assistant **Steve Reid, C.E.T.**
Weather **Mostly Over Cast with some Sunny Periods**

Low/High **10 °c 17 °c**

AADT **0** Latitude **44.32547900**
Lanes **1** Longitude **-76.15939800**
Skew **0 °** Orient **E-W**
Speed **40 km/h** Road Width
Truck Load Posting

Component Inspection Information

Concrete Wear Surface (1) Defects **2.0%** **Minor Abrasion**
Turn Table Damage **0.0%**
Length: **4 m** Maintenance **None**
Width: **3.7 m** Capital Rec. **None**
Height: *Wear associated with age occurring.*

Steel-Fabricated (2) Defects **0.0%**
Girders Damage **0.5%** **Minor Impact**
Length: **36.8 m** Maintenance **None**
Width: Capital Rec. **None**
Height: **2.5 m** *Coated since 2000 and appear to be in good condition. Some vehicle damage to interior rakers supporting the top flange.*

Steel Floor Beam (7) Defects **3.0%** **Minor Corrosion**
Floor Beams Damage **0.0%**
Length: **5 m** Maintenance **None**
Width: Capital Rec. **None**
Height: **0.8 m** *Corrosion appearing despite coating.*



Component Inspection Information

Stringers (6)	Defects 3.0%	Minor Corrosion
Stringers	Damage 0.0%	
Length: 36.8 m	Maintenance None	
Width:	Capital Rec. None	
Height: 0.6 m	<i>Evidence of corrosion through coating.</i>	
RC Wing Walls (4)	Defects 25.0%	Moderate AAR Cracking, Moderate Shallow Patches
Wing Walls	Damage 3.0%	Moderate Disintegration
Length:	Maintenance None	
Width: 3 m	Capital Rec. None	
Height: 4 m	<i>Masonry in generally good condition. Reinforced concrete has significant deterioration. SE corner worst</i>	
Stone Masonry Abutment (2)	Defects 0.0%	
Abutment Stem	Damage 0.0%	
Length:	Maintenance None	Partial Inspection
Width: 7 m	Capital Rec. None	
Height: 4 m	<i>Some pointing is missing, but generally in good condition.</i>	
Stone Masonry Pier (1)	Defects 0.0%	
Pier Column/Shaft	Damage 0.0%	
Length: 5 m	Maintenance None	Partial Inspection
Width: 5 m	Capital Rec. None	
Height: 3 m	<i>Pier was rehabilitated around 2000 and is in good condition as far as could be seen from shore. Little change in 2016.</i>	
Rocker or Roller Bearing (1)	Defects 0.0%	
Pier Bearings	Damage 0.0%	
Length:	Maintenance None	Partial Inspection
Width:	Capital Rec. None	
Height:	<i>The rollers for the turn table appear to be functional.</i>	
Water Channel (1)	Defects 0.0%	
Channel	Damage 0.0%	
	Maintenance None	
	Capital Rec. None	
	<i>Deep navigable channel.</i>	



Component Inspection Information

Embankment (2)	Defects 0.0%
Embankment	Damage 0.0%
	Maintenance None
	Capital Rec. None
	Stable.



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	✗	m ²	0.0	\$300	\$0
<i>Deck Concrete Overlay</i>	✗	m ²	147.2	\$350	\$0
<i>Deck Replacement</i>	✗	m ²	147.2	\$2,000	\$0
<i>Barrier Wall Replacement</i>	✗	m	60.8	\$1,500	\$0
<i>Expansion Joint</i>	✗	m	8.0	\$3,000	\$0
<i>Waterproof & Pave</i>	✗	m ²	80.0	\$100	\$0
<i>Bearing Replacement</i>	✗	Count	4.0	\$5,000	\$0
<i>Approach Guiderail</i>	✗	m	80.0	\$200	\$0

Other Work

\$0

Structural Items Subtotal \$0

Mobilization General Sitework 10% \$0

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$0

Total Rehabilitation Cost Estimate \$0

<i>Rec'd Investigations</i>	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	✗	✗	✗	✗	✓	✗	✗	✗

Recommended Capital Work Summary

Recommended Capital Year 0

Inspection Comments

Navigation lighting should be considered for this bridge. Bridge has a legal 24-24-32 tonne posting that is appropriate and should not need updating. Bridge was coated after 2010. Structural steel has a few minor perforations and other corrosion damage that has been generally halted with the coating system. Little change 2016.

Bridge Condition Index: 71.1 Parabolic Depreciation: 0.0 % Straight Line Depreciation: 0.0 %

Estimated Replacement Value: \$1,175,000

Estimated Remaining Service Life: 28 Years



Image 216



South elevation

Image 208



West approach

Image 209



East approach

Image 210



East deck end

Image 211



West deck end

Image 212



Typical concrete deck



Image 213



Typical steel deck

Image 214



Bent interior rakers on north side wall

Image 215



Typical side wall and railing on south side

Image 217



West abutment wall

Image 218



Pier with rotation system

Image 219



East span soffit



Image 220




Typical roller for rotating system

Image 222



East abutment wall

Image 221





North elevation

Image 223



Typical wing wall





Bridge Inspection Report

Power Canal Dam Bridge

Slab on Steel Girder	Site ID	9
Gananoque Waterfront Trail	District	
Town of Gananoque	Built	2015
Gananoque River	Length	41.8 m
55 meters north of Tanner st.	Width	3.65 m
	Spans	4
Span Arrangement (m's) 3.7,6.5,3.4,3.7		
Feature Under	Water	



Insp Date	May 5, 2016
Inspector	John Landry, EIT
Assistant	Steve Reid, C.E.T.
Weather	Mostly Over Cast with some Sunny Periods
Low/High	10 °c 17 °c

AADT	0	Latitude	44.32776300
Lanes	0	Longitude	-76.16635400
Skew	0 °	Orient	N-S
Speed	0 km/h	Road Width	3.65 m
Truck		Load Posting	

Component Inspection Information

Unprotected BSRC Deck (1)	Defects	0.0%	
Deck Surface	Damage	0.0%	
Length:	41.8 m	Maintenance	None
Width:	3.65 m	Capital Rec.	None
Height:	0.08 m		<i>New concrete deck 2016.</i>

Soffit (1)	Defects	0.0%	
Deck Soffit	Damage	0.0%	
Length:	41.8 m	Maintenance	None
Width:	3.65 m	Capital Rec.	None
Height:			<i>New steel deck pan.</i>

Ped Steel Post & Panel (2)	Defects	10.0%	Minor Tarnishing, Minor Corrosion
Railings	Damage	0.0%	
Length:	41.8 m	Maintenance	None
Width:		Capital Rec.	None
Height:	1.1 m		<i>Original pedestrian railing recycled.</i>



Component Inspection Information

Steel-Rolled (16)	Defects 10.0% Minor Corrosion
Girders	Damage 0.0%
Length: 17.3 m	Maintenance None
Width:	Capital Rec. None
Height: 0.3 m	<i>Girders appear to be of reclaimed material.</i>

RC Abutment Wall (2)	Defects 0.0%
Abutment Stem	Damage 0.0%
Length: 3.6 m	Maintenance None
Width:	Capital Rec. None
Height: 3.5 m	<i>North abutment refaced in 2015.</i>

RC Column (3)	Defects 0.0%
Pier Column/Shaft	Damage 0.0%
Length: 3.6 m	Maintenance None
Width:	Capital Rec. None
Height: 3.5 m	<i>refaced 2015.</i>

Water Channel (1)	Defects 0.0%
Channel	Damage 0.0%
	Maintenance None
	Capital Rec. None
	<i>No concerns.</i>



Capital Needs Cost Estimate Break-Down

Item	Req'd	Units	Quantity	Unit Price \$	Estimated Cost
<i>Misc Concrete Repairs</i>	X	m ²	0.0	\$300	\$0
<i>Deck Concrete Overlay</i>	X	m ²	152.6	\$350	\$0
<i>Deck Replacement</i>	X	m ²	152.6	\$2,000	\$0
<i>Barrier Wall Replacement</i>	X	m	65.8	\$1,500	\$0
<i>Expansion Joint</i>	X	m	7.3	\$3,000	\$0
<i>Waterproof & Pave</i>	X	m ²	80.0	\$100	\$0
<i>Bearing Replacement</i>	X	Count	32.0	\$5,000	\$0
<i>Approach Guiderail</i>	X	m	80.0	\$200	\$0

Other Work

\$0

Structural Items Subtotal \$0

Mobilization General Sitework 10% \$0

Estimated Traffic Management & Civil Items \$0

Contract Admin & Contingencies 20% \$0

Total Rehabilitation Cost Estimate \$0

<i>Rec'd Investigations</i>	Deck Conditon Survey	Enhanced Inspection	Underwater Investigation	Ice Inspection	Boat Inspection	Structure Evaluation	Load Posting	Planning Study
	X	X	X	X	X	X	X	X

Recommended Capital Work Summary

Recommended Capital Year 0

Inspection Comments

Structure replaced in 2015.

Bridge Condition Index: 88.3 Parabolic Depreciation: 72.4 % Straight Line Depreciation: 64.4 %

Estimated Replacement Value: \$826,000

Estimated Remaining Service Life: 69 Years



Image 159



East elevation

Image 153



North approach

Image 154



South approach

Image 155



Upstream channel west

Image 156



Downstream channel east

Image 157



Typical deck





Typical railing




South span soffit



North span soffit



Old south pier






Structure Summary Statistics

Structure Age Histogram




Average Age	67
Youngest Age	1
Oldest Age	122
Structure Count	9

Structure Deck Area Histogram



Average Deck Area	226 m²
Min Deck Area	7 m²
Max Deck Area	675 m²
Total Deck Area	2,037 m²

Structure Deck Area per Age Histogram



Deck area < 20 yrs old	179 m²
Deck area < 50 yrs old	179 m²
Deck area > 50 yrs old	1859 m²



Bridge List

Bridge ID	Name	Route	Length	Width	Spans	Const Yr
1	Black (Snappers) Bridge	Gananoque Waterfront T	36.0	6.2	1	1924
2	Wood Bridge	Gananoque Waterfront T	5.8	1.2	1	2004
3	Hudson Bridge	Machar St	39.1	5.2	1	1911
4	Rail to Trail Bridge	Gananoque Waterfront T	31.6	1.8	3	1920
5	Power Canal Ped Bridge	Gananoque Waterfront T	9.0	2.1	1	2015
6	King Street Bridge	King St. East	51.1	13.2	1	1930
7	King Street Pedestrian Bridge	Gananoque Waterfront T	71.9	7.7	2	1927
8	Water Street Swing Bridge	Water Street	36.8	4.0	1	1894
9	Power Canal Dam Bridge	Gananoque Waterfront T	41.8	3.7	4	2015

Those bridges where the span is highlighted in amber are not subject to the Ontario Statute for biennial inspection.



Capital Needs Report

Year **2017**

Structure ID	Name	Route	Work	Cost
1	Black (Snappers) Bridge	Gananoque Waterfront Trail	Retaining Walls	\$60,000
4	Rail to Trail Bridge	Gananoque Waterfront Trail	Replace	\$660,000
Sum for Year				\$720,000
Percentage of Grand Total				14.6%

Year **2018**

Structure ID	Name	Route	Work	Cost
7	King Street Pedestrian Bridge	Gananoque Waterfront Trail	Replace timber deck	\$224,000
Sum for Year				\$224,000
Percentage of Grand Total				4.6%


Year **2020**

Structure ID	Name	Route	Work	Cost
3	Hudson Bridge	Machar St	Replace	\$3,972,000
Sum for Year				\$3,972,000
Percentage of Grand Total				80.8%




Total Capital Needs (m's) \$4,916,000 Over 4 Years

Capital Expenditure by Year



Capital Expenditure by Structure Type



Bridge Maintenance Report

Bridge ID	Name	Road	Component	Maintenance
1	Black (Snappers) Bridge	Gananoque Waterfront Trail	Diagonal/Post/Hangar	Remove debris
			Debris collected at bottom chord gussets.	
			Delineator	Replace Sign
			Missing one delineator in SW corner.	
			Diagonal/Post/Hangar	Remove debris
			Debris collected at gussets at bottom chord.	
			Half Through or Pony	Remove debris
			Good condition except for debris at gusset locations.	
			Embankment	Slope revetment
			Southeast timber retaining wall has failed. Excessive erosion should be repaired. Timber retaining wall in other corners beginning to deteriorate.	
	RC Ballast Wall	Repair Damage		
Timber blocking at both deck ends is decayed and requires replacement as a maintenance item.				
	Steel Sliding Plate	Remove debris		
Debris around bearings should be removed. Disintegration of abutment wall encroaching on bearings.				
3	Hudson Bridge	Machar St	Timber-Laminated	Local repair
			Timber has major rutting, allowing screws and steel spacers to protrude through deck. Recommend placing asphalt padding until deck can be replaced.	
			Steel Sliding Plate	Power Wash
Severely corroded. Debris around bearings is increasing rate of corrosion in bearings and end Diagonals.				
4	Rail to Trail Bridge	Gananoque Waterfront Trail	Embankment	Slope revetment
			Stable, groomed, with some local erosion. An old timber retaining wall in NW quadrant has failed.	
			Wood Post Wood Rail	Replace Bracing
Cleats supporting rakers exhibit decay and require spot replacement. Railing system is secure.				



Bridge ID	Name	Road	Component	Maintenance
6	King Street Bridge	King St. East	X- Joint Conventional	Remove Debris
<i>Good condition. Silty debris in seal.</i>				
7	King Street Pedestrian Bridge	Gananoque Waterfront Trail	Embankment	Remove Brush/Trees
<i>Extremely dirty under west span. Infilling is preventing good air circulation under west span.</i>				
			Timber Wear Surface	Local repair
<i>Bridge deck has a number of decayed planks. Repair locally as a maintenance item. Structure experienced punch through failure at north end of north span. Hole from punch through covered by plywood sheets. Recommend limiting structure to pedestrians only. Wood stringers are expected to be starting to decay.</i>				



Schedule D KEY PLAN

Attached to this Schedule is the Key Plan for the 2018 OSIM Inspections

LEGEND

LOCATIONS OF BRIDGES

BLACK (SNAPPERS) BRIDGE

WOOD BRIDGE

HUDSON BRIDGE

RAILS TO TRAILS BRIDGE

POWER CANAL DAM BRIDGE

POWER CANAL
PEDESTRIAN BRIDGE

KING STREET
PEDESTRIAN BRIDGE

KING STREET BRIDGE

WATER STREET SWING BRIDGE

THE CORPORATION OF THE TOWN OF



Canadian Gateway to the 1000 Islands

DATE:
JUNE 2018

SCALE:
N.T.S

DRAWING NAME:
SCHEDULE "D"
KEY PLAN